

## UMPS

After KEIL C complier the file, we use the execute file Hin2bin to convert the hex file to binary file  
Here is the command code >> Hin2bin Driver.hex

