



# TURNING JIG FOR BOWL FOOT



BASE PLATE



FRONT PLATE

## **KEY**

- 1.) Use 3/8" Plywood, round all edges
- 2.) OD and ID dimension to fit your Lathe and the size bowls you are turning
- 3.) Drill 4 clearance holes for 1/4" carriage bolts, use wing nuts and washers
- 4.) Screw Lathe Face plate to back of Base Plate

## **SUGGESTIONS FOR USE**

- 1.) Use rubber pads cut to same dimension as above plates, to cushion bowl from being dented by plywood
- 2.) Make sure bowl is centered and secured before cutting
- 3.) Make sure all bolts and rotating members clear all parts of your lathe!!!!
- 4.) You should use different length Carriage bolts for each size bowl you use to minimize how far they stick out.

**USE AT YOUR OWN RISK, THIS DRAWING IS FOR DISCUSSION PURPOSES ONLY**

# TURNING JIG FOR BOWL FOOT

