

C 414ULS/C 414TL

Under certain conditions (setting of switches, supply voltage) it might happen that the microphone starts oscillating at around 4 kHz. The following modification will solve this problem. From the last production on this problem is solved by a change in inductivity of the HF transformer TR 101.

