


Mastering Solid Edge V18

Step-by-Step



Hui Zhang, Ph.D., P.Eng.

www.geocities.com/zhanghui1998

Table of Contents

Chapter 1 Introduction to Solid Edge.....	1
1.1 Solid Modeling Fundamentals.....	2
1.2 Solid Edge User Interface.....	3
1.3 Customize Solid Edge	13
1.4 Mouse Usage	15
1.5 How To Use This book.....	16
Chapter 2 Sketch and Extruded Features.....	17
2.1 Sketch and Profile.....	17
2.1.1 Sketch Elements	17
2.1.2 Constraints	35
2.1.3 Dimensions	38
2.2 Extruded Features.....	43
2.2.1 Protrusion.....	43
2.2.2 Cutout	46
2.2.3 Feature Modification	46
2.3 Extruded Feature Project: Dovetail Slide	49
2.3.1 Start Solid Edge Part, and Setup Properties	50
2.3.2 Create Base Feature.....	52
2.3.3 Create Dovetail Cutout	54
2.3.4 Create Side Slot Using Cutout.....	55
2.3.5 Cut Front and Back Slots.....	56
2.3.6 Get Part Physical Properties	57
Chapter 3 Holes and Threads	59
3.1 Simple Hole	60
3.2 Threaded Hole	63
3.3 Tapered Hole	64
3.4 Counterbore Hole	66
3.5 Countersink Hole.....	67
3.6 Thread.....	68
3.7 Project: Bracket	71
3.7.1 Create a Base	72
3.7.2 Add a Boss.....	73
3.7.3 Cut a Pocket.....	75
3.7.4 Cut a Fillet	76
3.7.5 Drill Counterbore Holes	78
3.7.6 Drill Countersink Holes.....	80
3.7.7 Drill a Threaded Hole	81
Chapter 4 Rounds and Chamfers.....	83
4.1 Round.....	83
4.1.1 Constant Radius Round/Fillet.....	83
4.1.2 Variable Radius Round.....	87
4.1.3 Blend Round	90
4.2 Chamfer	93
4.2.1 Equal setback Chamfer	93

Table of Contents

4.2.2 Angle and Setback Chamfer	94
4.2.3 2 Setbacks Chamfer	94
4.3 Project: Movable Jaw	96
4.3.1 Create Jaw Body	97
4.3.2 Create a Disk Boss, Cut a Hole and Add a Round and a Chamfer.....	98
4.3.3 Cut a Rectangular Socket and Its Round Corners	102
4.3.4 Create Corner Rounds	103
4.3.5 Drill Screw Holes	105
Chapter 5 Reference Plane.....	107
5.1 Coincident Plane.....	108
5.2 Parallel Plane	109
5.3 Angled Plane.....	109
5.4 Perpendicular Plane	111
5.5 Coincident Plane by Axis	113
5.6 Plane Normal to Curve	114
5.7 Plane by 3 Points	115
5.8 Project: Vertical Bearing Support.....	116
5.8.1 Create a base	118
5.8.2 Create a Parallel Plane, and a slot boss for creating the slot body	118
5.8.3 Create an angled plane and a slot body	119
5.8.4 Cut the slots on the slot body and the base.....	121
5.8.5 Add hole bosses for drilling holes	122
5.8.6 Drill holes and add rounds.....	124
Chapter 6 Copy, Mirror and Pattern Features	131
6.1 Copy Features	131
6.2 Mirror Features	133
6.3 Pattern Features	134
6.3.1 Rectangular Pattern.....	134
6.3.2 Circular Pattern.....	137
6.4 Project 1: Copy and Mirror – Shaft Guide	139
6.4.1 Create Triangle Base	140
6.4.2 Add Boss and Shaft Hole.....	141
6.4.3 Cut Keyway and Drill Hole	142
6.4.4 Copy and Mirror Hole	144
6.4.5 Add Round and Chamfer	145
6.5 Project 2: Rectangular Pattern – Bearing Block Cover	146
6.5.1 Create a cover	147
6.5.2 Drill bolt hole and pattern it using rectangular pattern.....	148
6.5.3 Cut counterbore, and mirror it	150
6.6 Project 3: Circular Pattern – Vise Base	150
6.6.1 Create the base.....	151
6.6.2 Cut a circular slot on the base.....	152
6.6.3 Create an ear and holes on the base.....	154
6.6.4 Generate a circular pattern of the ear and hole	155
Chapter 7 Revolved Features	157
7.1 Profiles for Revolved Features	157

Table of Contents

7.2 Revolved Protrusion	158
7.3 Revolved Cutout.....	162
7.4 Project – V-Pulley	163
7.4.1 Create Pulley Stock using Revolved Protrusion.....	164
7.4.2 Create Bearing Bore using Revolved Cutout	164
7.4.3 Cut Trapezoid Circular Slots using Revolved Cutout and Mirror.....	165
7.4.4 Create V-Belt Groove by Revolved Cutout and Copy it.....	167
7.4.5 Add Chamfer and Rounds	169
Chapter 8 Sweep Features	171
8.1 Single-Cross Section, Single-Path Sweep Features.....	172
8.1.1 Create a sweep feature by means of creating profile and path first.....	172
8.1.2 Create a sweep feature within Sweep Command	174
8.1.3 Edit Sweep Feature.....	175
8.2 Multiple Path and Cross Section (MPC) Sweep Features	175
8.2.1 Create a MPC sweep by means of creating profile and path first	175
8.2.2 Create a MPC sweep within Sweep Command.....	178
8.3 Project – Cranking Lever.....	179
8.3.1 Create a crank head using revolved feature.....	180
8.3.2 Add a handle body using sweep	182
8.3.3 Create a handle and hole by revolved feature.....	185
8.3.4 Create a rib, and rounds on the crank lever	186
Chapter 9 Loft Features	189
9.1 Cross-sections, Vertex Mapping, and Guide Curves.....	189
9.2 Construct Loft Features by Drawing Cross-sections and Guide Curves	191
9.3 Construct Loft Feature by Selecting Cross-sections and Guide Curves.....	197
9.4 Loft Feature Modification	198
9.5 Project: Machine-Vise Handle.....	199
9.5.1 Create a Handle Head	200
9.5.2 Add a Handle Link	201
9.5.4 Attach a Handle	203
9.5.4 Cut a Pocket.....	204
9.5.5 Create Chamfer and Rounds.....	204
Chapter 10 Draft, Thin Wall, Thin Region, and Thicken	207
10.1 Draft Features	207
10.1.1 Draft from Plane	208
10.1.2 Draft From Edge.....	209
10.1.3 Draft From Parting Surface	211
10.1.4 Draft from Parting Line	212
10.2 Thin Wall, Thin Region, and Thicken Features	213
10.2.1 Thin Wall	214
10.2.2 Thin Region	215
10.2.3 Thicken	217
10.3 Project: Power Socket Cover.....	218
10.3.1 Create Cover Body and Screw Poles	219
10.3.2 Create Thin Walls.....	224
10.3.3 Create Slot, Hole and Cuts on The Cover Body	227

Table of Contents

10.3.4 Create Plug Bosses and Holes	229
Chapter 11 Curves, Surfaces, and Part Construction.....	233
11.1 Curves.....	233
11.1.1 Intersection Curve.....	233
11.1.2 Project Curve	235
11.1.3 Cross Curve	238
11.1.4 Keypoint Curve.....	239
11.1.5 Curve By Table.....	240
11.1.6 Contour Curve	242
11.1.7 Derived Curve.....	243
11.1.8 Split Curve.....	244
11.1.9 Intersection Point.....	245
11.2 Surfaces and Surface Transformation.....	246
11.2.1 Extruded, Revolved, Swept, and Lofted Surfaces	247
11.2.2 Bounded Surface.....	248
11.2.3 Offset Surface	249
11.2.4 Copy Surface	250
11.2.5 BlueSurf.....	251
11.2.6 BlueDot.....	255
11.2.7 Delete Faces.....	257
11.2.8 Trim Surface	258
11.2.9 Extend Surface.....	259
11.2.10 Stitched Surface and Shown Non-Stitched Edges.....	260
11.2.11 Replace Face.....	262
11.3 Part Construction	263
11.3.1 Part Copy	263
11.3.2 Divide Part.....	266
11.3.3 Boolean Feature	267
11.4 Project: Fan Blade	269
11.4.1 Create Boundary Surfaces by Revolved Surfaces	270
11.4.2 Build Fan Blade by Curves and Lofted constructions.....	272
11.4.3 Add Fan Hub, and Cut Shaft Hole.....	281
11.4.4 Pattern Blade	282
Chapter 12 Helical and Normal Features.....	284
12.1 Helical Features	284
12.2 Normal Features, and Text Profile	288
12.2.1 Text Profile	288
12.2.2 Normal Feature	290
12.3 Project: Fixed Jaw	292
12.3.1 Create Jaw Body	293
12.3.2 Create Cutouts on Jaw Body	295
12.3.3 Create Trapezoid Thread Using Helical Cutout	299
12.3.4 Create Jaw, Platform, and Screw Holes	301
Chapter 13 Rib, Web Network, and Lip	310
13.1 Rib	310
13.2 Web Network.....	313

Table of Contents

13.3 Lip.....	316
13.4 Project: Rotary Yoke	317
13.4.1 Create Yoke Base	318
13.4.2 Create Cylinder Boss and Cut Shaft Hole	321
13.4.3 Create Ribs	322
13.4.4 Add Rounds	324
Chapter 14 Variables and Family of Parts.....	326
14.1 Variables	326
14.1.1 Drive a dimension with a formula and another dimension.....	326
14.1.2 Drive a dimension with a value from a Microsoft Excel spreadsheet ...	332
14.1.3 Drive a dimension from a Visual Basic function or subroutine	335
14.2 Family of Parts	337
14.2.1 Define Master File of Family of Parts	337
14.2.2 Populate Family Members.....	340
14.2.3 Suppressing and Resuming Features	341
14.2.4 Add or Delete Variables	342
14.2.5 Add, Copy, Rename and Delete Family Members	343
14.2.6 Modify a Family of Parts.....	344
14.3 Project: Flat Slotted Screw	344
14.3.1 Create Flat Slotted Screw	344
14.3.2 Change Variable Names and Add Formulas	346
14.3.3 Create a Family of Flat Slotted Screws	347
14.3.4 Populate Members of Family of Flat Slotted Screws.....	349
Chapter 15 Feature Edit, Reorder, and Model Roll Back.....	350
15.1 Feature Edit.....	350
15.2 Feature Reorder	350
15.3 Feature Suppress/Unsuppress	352
15.4 Model Rollback	352
15.5 Project: Oil Pan.....	353
15.5.1 Create Rim Body and Modify It By Editing Sketch.....	354
15.5.2 Create Oil Pan Body	356
15.5.3 Create Holes	357
15.5.4 Shell The Oil Pan, and Reorder The Thin Wall Before Holes	359
15.5.5 Insert A Fillet on The Bottom of Oil Pan by Roll Back	361
Chapter 16 Sheet Metal.....	364
16.1 Sheet Metal Settings	364
16.2 Tab	366
16.3 Flange	367
16.4 Contour Flange, and Lofted Flange.....	373
16.4.1 Contour Flange – Base Feature	373
16.4.2 Contour Flange – Add to Part.....	374
16.4.3 Hem	378
16.4.4 Lofted Flange.....	379
16.5 Normal Cutout, Cutout	381
16.6 Jog.....	381
16.7 Bend, Unbend, and Rebend	383

Table of Contents

16.8 Break Corner, Close Corner	387
16.9 Dimple, Louver, Drawn Cutout, and Bead.....	389
16.9.1 Dimple	390
16.9.2 Louver.....	391
16.9.3 Drawn Cutout	394
16.9.4 Bead	396
16.10 Flatten Sheet Metal Part, and Add Features in The Part Environment	398
16.11 Sheet Metal Project:.....	402
16.11.1 Create a Tab.....	403
16.11.2 Add a Bend to the Tab.....	404
16.11.3 Attach Two Flanges on the Side Edges of the Tab.....	405
16.11.4 Add a Tab to the Front Edge of the Part.....	406
16.11.5 Create a Jog on the Front Tab.....	407
16.11.6 Add Two Contour Flanges on the Edge Flanges.....	408
16.11.7 Create a Rolled Hem on the Tip of The Front Flange	411
16.11.8 Break the Corners and Add Screw Holes	412
16.11.9 Save The Hinge As Flat.....	415
Chapter 17 Assembly.....	416
17.1 Place Parts or Subassemblies into Assembly	416
17.2 Assembly Relationships	417
17.2.1 Ground , Mate and Reduced Steps	418
17.2.2 Planar Align	421
17.2.3 Axial Align	422
17.2.4 Insert	423
17.2.5 Connect	424
17.2.6 Angle	427
17.2.7 Tangent	428
17.2.8 Cam.....	430
17.2.9 FlashFit	431
17.2.10 Edit, Delete and Suppress Relationships	432
17.3 Create New Part in-Place.....	433
17.4 Pattern Parts in Assembly	435
17.5 Create Systems Library	437
17.6 Assembly Layout.....	440
17.7 Alternate Assemblies.....	444
17.7.1 Alternate Position Assemblies.....	445
17.7.2 Family of Assemblies	448
17.8 Exploded Assembly	451
17.8.1 Automatic Explode	451
17.8.2 Explode	452
17.8.3 Adjust Spread Distance	454
17.8.4 Reposition.....	454
17.8.5 Remove	455
17.8.6 Collapse and Unexplode	455
17.8.7 Add Joggle and Remove Joggle	456
17.8.8 Bind Subassembly, and Unbind Subassembly	457

Table of Contents

17.8.9 Move Part	457
17.9 Other Assembly Tools	458
17.9.1 Multi-Part Cutout.....	459
17.9.2 Capture Fit.....	460
17.9.3 Move Part	461
17.9.4 Replace	463
17.9.5 Transfer / Disperse.....	464
17.9.6 Show / Hide / Show Only /Activate Part / Inactivate Part.....	467
17.10 Assembly Project: Mechanic Vise Assembly.....	469
17.10.1 Assemble Base and Bolt M8, Create Spherical Head Bolt In-Place	472
17.10.2 Assemble Fixed Jaw, Washer 8, Lock Nut, Lock Handle and Handle Head.....	475
17.10.3 Install Guide Bar, Movable Jaw, and Washers.....	481
17.10.4 Add Screw, Cotter Pin, Handle, and Handle Head.....	484
17.10.5 Install Jaw Plates, and Screw M3	487
17.10.6 Explode Assembly	489
Chapter 18 Weldment	492
18.1 Get Weldment Components.....	492
18.2 Prepare The Components for Welding	494
18.3 Add Weld Beads and Weld Lables.....	496
18.3.1 Fillet Weld	497
18.3.2 Label Weld	500
18.3.3 Stitch Weld	502
18.3.4 Construct Weld Beads With Protrusion Tools	503
18.4 Post-Weld Machining	504
18.5 Create Feature Patterns and Stand-alone Documents.....	504
18.6 Create Weldment in Weldment Assembly Environment	504
18.7 Weldment Project: Bearing Support.....	505
18.7.1 Build Parts and Assembly	506
18.7.2 Create Preparation Features.....	511
18.7.3 Add Weld Beads.....	512
18.7.4 Construct Post-Machining Features	517
Chapter 19 Drawing Template and Views	522
19.1 Define Drawing Standards.....	522
19.2 Create Customized Template.....	529
19.2.1 Setup Sheet Size and Orientation	530
19.2.2 Add a border to the sheet and construct a title block.....	532
19.2.3 Add texts, property texts and company's logo into the title block	534
19.2.4 Save the template into the default folder of the Solid Edge	538
19.2.5 Setup The Working Sheet Format	538
19.3 Generate Drawing Views.....	539
19.3.1 Drawing View Wizard.....	540
19.3.2 Principle View	544
19.3.3 Auxiliary View	545
19.3.4 Cutting Plane and Section View	546
19.3.5 Broken-Out Section View	550

Table of Contents

19.3.6 Detail View.....	551
19.3.7 Update Views	553
19.3.8 Broken Views	553
19.3.9 Crop Views	554
19.4 Project: Vertical Bearing Support Drawing.....	555
19.4.1 Sheet Setup and Principle View Creation.....	555
19.4.2 Create a Top View and a Left View	556
19.4.3 Create a Section View	557
19.4.4 Create an Auxiliary View	558
19.4.5 Create a Detail View.....	559
Chapter 20 Drawing Detailing.....	560
20.1 Dimensions	560
20.1.1 Retrieve Dimensions.....	561
20.1.2 Chamfer Dimension.....	562
20.2 Annotations.....	563
20.2.1 Center Line, Center Mark and Bolt Hole Circle.....	563
20.2.2 Leader and Callout	567
20.2.3 Surface Texture Symbol, Weld Symbol, and Edge Condition	569
20.2.4 Feature Control Frame, Datum Frame, and Datum Target.....	572
20.2.5 Text.....	576
20.3 Hole Table	577
20.4 Project: Bracket Drawing	581
20.4.1 Create Drawing Views.....	581
20.4.2 Retrieve Model Dimensions	583
20.4.3 Add Radius Dimension and Center Lines	584
20.4.4 Add Hole Callouts	585
20.4.5 Add Dimension Tolerance and Surface Texture Symbol	586
20.4.6 Add Text and Property Text	587
Chapter 21 Assembly Drawings	590
21.1 Bill of Materials (BOM).....	590
21.2 Balloons	595
21.3 Remove Hatch from Selected Part in Section Views	596
21.4 Project: Mechanic Vise.....	597
21.4.1 Create Assembly Views.....	597
21.4.2 Remove Hatch from Some Parts	599
21.4.3 Add Dimensions, BOM, and Balloons	600
21.4.4 Add A Drawing Sheet and An Exploded View.....	603