



Scheme of the installation for the dimer evaporation, conversion to monomer and controlled supply to vacuum chamber for deposition of POLYPARAXYLYLENE films.